

STDN DAILY REPORT FOR GMT DAYS 24, 25 AND 26, June 2002

Part I. Operations

24 JUNE

A.SN Anomalies:

1. STGT/ERBS Support

24/0626-0630Z

POCC reported late acquisition reason unknown, 2 forwards reacq's followed by and auto-failover to MAR4 and the event acquired lock. CDS DR # 31026

TDE MAF/R3 3 Min. 3 Sec. Svc/Data Loss

B. ISS Anomalies - None.

C.GN Anomalies:

1. WGS/FAST Support

24/1851-1858Z

This event was scheduled as a Low elevation pass. POCC scheduling error. CDS ID # 31033

TOTS-3 7 Min. Svc/Data Loss (Non-Recov)

D. NOAA-M was launched at 175/182305Z.

25 JUNE

- A. SN Anomalies None.
- B. ISS Anomalies None.

C.GN Anomalies:

1. AGS/SWAS Support

25/1343-1356Z

This event was not support due to a scheduling problem. Upon further investigation this support was not included on the current schedule. CDS ID # 31031

TOTS-1 13 Min. Svc/Data Loss

2. WGS/SEAWIFS Support

25/1705-1706Z

11M antenna had to be taken out of autotrack due to oscillations. CDS ID # 31035

11 Meter 40 Sec. Svc/Data Loss (Recov)

3. SGS/QUIKSCAT Support

25/1920-1936Z

Station reported antenna failed to positioned correctly. Due to incorrect ephemeris attached to master schedule CDS ID # 31036

11 Meter Antenna 15 Min. 19 Sec. Svc/Data Loss

4. AGS/AQUA Support

25/2246-2250Z

POCC reported S-Band telemetry service loss due to weather. CDS ID # 31037

11 Meter Antenna 3 Min. Svc/Data Loss (Recov)

D. The Data Services Management Center Space Network transition was completed at approximately 2200Z.

JUNE 26

A.SN Anomalies:

1. WSC/MULTIPLE Support

26/1642-1740Z

During offline troubleshooting of the NCC/DSMC firewall, a heartbeat cable between the two firewalls was removed. Resulting in no UPD'S or GCMR capability. CDS DR # 31039

Multiple 58 Minutes of service loss

2. WSGT/HST Support

26/2336-2344Z

WSC scheduling error operator inadvertently changed the schedule MA return service. CDS DR # 31041

TDW SSAF/MAR 8 Min. Svc/Data Loss

- B. ISS Anomalies None.
- C. GN Anomalies:

1. SGS/AQUA Support

26/0844-0857Z

SCC software crashed when operator tried to manually turn uplink on using the Control/ Status menu. CDS ID # 31038

11 Meter Antenna 13 Min Svc/Data Loss (Non-Recov)

Part II. Operation Engineer Report:

6/24/2002

System Anomalies: 0040Z - Operations called the OPS beeper due to a scheduling problem at JSC.

0527Z - JSC back online, JSC replaced interface card in their Nascom 2000 system at JSC.

6/25/2002

System Anomalies: 1309Z - CCS control was taken away by someone the system would not allow the OE to connect to the system through the console.

1444Z - VAX1 was halted for preparation of database transition (DSMC).

1605Z - SPSR, ROSE, and VAX1 was brought up at this time. (DSMC transition)

1618Z - ACRS, and NPG's came up at this time.

1747Z - The DSMC transition was completed at this time. Operations has transitioned to WSGT, WSGT.

Part III. Scheduled Activities - None.

Part IV Forecast Changes - None.

* 1.) M2107LS (STS-107/SPACEHAB/ INDEFINITE.,2002 T-0 = FREESTAR) UNKNOWN